

SWITCH LIST AND SERVICE INSTRUCTIONS

PERISHABLE FREIGHT

From BUTTE, MONT To LIMA, MONT APRIL 8, 1966
 Train No. # 278 Eng. No. 197 R-KIRKHAM Phelps Conductor.

TO AGENT OR INSPECTOR

Carload Perishable Freight must be serviced in accordance with waybill instructions shown below. Position of ventilators to be recorded under "Arrival" and "Departure" columns, show "O" for Open, "C" for Closed.

INITIAL	CAR NUMBER	CLASS	TARE	GROSS TONS	CONTENTS	DESTINATION	WAYBILL INSTRUCTIONS	ARR.	DEP.
1	TTX	250280	TOFC		XTR	OAKLAND CALIF.			
2	UP	193175	B		B L B	PT ARTHUR TEXAS			
3	UP	196482	B		-	-			
4	GN	18379	B		WHEAT	SALT LAKE CITY UT			
5	UP	498368	DF		MTY	POCA, IDAHO			
6	GN	71348	CH		CEMENT	MICHAUD IDAHO			
7	GN	71411	CH		-	MERIDIAN IDAHO			
8	GN	56308	MXSD		MTY	HINKLE OREGON			
9	GN	56066	SD		-	-			
10	GN	55222	SD		-	-			
11	GN	56X306	SD		-	-			
12	GN	56133	SD		-	-			
13	GN	55302	SD		-	-			
14	GN	56123	SD		-	-			
15	GN	55762	SD		-	-			
16	UP	88764	H		MTY	SALT LAKE CITY UT			
17	UP	30940	G		-	POCA, IDAHO			
18	UP	30065	G		-	-			
19	RBWX	64276	DF		HONEY	WENDELL IDAHO			
20	UP	29871	B		MTY	POCA, IDAHO			
21	PFE	48383	R		-	-			
22	GN	52026	B		WHEAT	SALT LAKE CITY UT			
23	B&O	272645	B		-	-			
24	GN	55317	SD		MTY	HINKLE OREGON			
25	PFE	44765	R		-	POCA, IDAHO			
26	UTLX	67517	T		ASPHALT	BOISE, IDAHO			
27	NPM	404	MR		CHEESE	POCA, IDAHO	MECH REFGN		
28	UP	192717	B		MTY	-			
29	UP	185427	B		-	-			
30	GATX	XX58793	T		-	WILMINGTON CALIF			
31	UP	198523	B		-	POCA, IDAHO			
32	UP	191286	B		-	-			
33	UP	192082	B		-	-			
34	UP	198473	B		-	-			
35	UP	193312	B		-	-			
36	UP	12076	CH		MTY	DON IDAHO			
37	UP	12331	CH		-	MONTPELIER IDAHO			
38	UP	12029	CH		-	-			
39	GN	33162	B		WHEAT	SALT LAKE CITY UT			
40	RKE	21088	B						
41	ATSF	35412							
42	C&NW	6546							
43	millw	51366			Barytes	Craig			
44	K	17728			Lbr	Mo. Platte			
45	C&NW	26110			Phywood	Millard			
46	SP	314436			Shakes	Colo Spgs.			
47	millw	30065			Lbr	Pueblo			
48	GATX	38985	T		Y. Phos	Richmond			

This space is used for binding and should not be used for reporting Cars.

SWITCH LIST AND SERVICE INSTRUCTIONS

PERISHABLE FREIGHT

From B Lima To Ho Falls 4/9 1966
 Train No. 278 Eng. No. 197 Phelps Conductor.

TO AGENT OR INSPECTOR

Carload Perishable Freight must be serviced in accordance with waybill instructions shown below. Position of ventilators to be recorded under "Arrival" and "Departure" columns, show "O" for Open, "C" for Closed.

INITIAL	CAR NUMBER	CLASS	TARE	GROSS TONS	CONTENTS	DESTINATION	WAYBILL INSTRUCTIONS	ARR.	DEP.
1	GATX	38902	T		Y. Phos	So. Gate			
2	UTLX	66614			fuel oil	185			
3		66819							
4		62658							
5		61879							
6		62005							
7		61860							
8	Pfe	42860	R		Spuds	Wabunha	Dillon 2 1/2 PC D		e
9		47616							
10		3150							
11	up	192908	B		wheat	Vancouver			
12		192371							
13	pep	31809	R		Spuds	Winchester	Dillon 2 1/2 PC D		C
14	Pfe	3780				MT Vernon			
15		10126							
16	up	284419	B		Talc	Open			
17		42196	SI		x	185			
18		49015							
19		42128							
20		45847							
21		24141	B		mdr	1061	Bukin 11 X 51		
22									
23									
24									
25									
26									
27									
28									
29									
30									
31									
32									
33									
34									
35									
36									
37									
38									
39									
40									
41									
42									
43									
44									
45									
46									
47									
48									

Engl Thompson

37-33-3745

This space is used for binding and should not be used for reporting Cars.