

STATION RECORD OF TRAIN MOVEMENTS

C. T. 355-B REV.

THE PENNSYLVANIA RAILROAD COMPANY

| REGION

STATION

DATE

OPERATOR	ON DUTY	OFF DUTY	LEVERMAN	ON DUTY	OFF DUTY	WEATHER	Temp.	Time	INSTRUCTIONS
E. L. Barton	11:00 P.M.	7:00 A.M.	—	— M	— M	Clear	58°	7:00 P.M.	1. This record shall be made at each station, office, or place from which the time of arrival, departure, or passing of trains is reported by telephone.
G. W. Sanders	7:45 A.M.	3:00 P.M.	—	— M	— M	Clear	88°	3:00 P.M.	2. Each operator and leverman shall enter time on and off duty in the space provided.
A. A. Adams	3:00 P.M.	11:00 P.M.	—	— M	— M	Cloudy	70°	11:00 P.M.	
E. L. Barton	11:00 P.M.	7:00 A.M.	—	— M	— M				

TRANSFER RECORD

TRAIN ORDERS TO BE DELIVERED

AT 7:00 a.m.

AT 36 M

AT 11:00, P.M.

MESSAGES TO BE DELIVERED

AT

No
76

OVERDUE TRAINS

$$\#7_1 = 22 - \frac{w_3}{3} + \frac{w_1}{3} - 2$$

Worse
No

no
no

TRAIN ORDER SIGNAL DISPLAYED

None None
None

None None
Adams

Bartos

READ, UNDERSTOOD AND SIGNED

West WAR

East WARD

STATION RECORD OF TRAIN MOVEMENTS

C. T. 355-B REV.

THE PENNSYLVANIA RAILROAD COMPANY

REGION

1. STATION

DATE:

OPERATOR	ON DUTY	OFF DUTY	LEVERMAN	ON DUTY	OFF DUTY	WEATHER	Temp.	Time	INSTRUCTIONS
<i>E. L. Barton</i>	11:00 M	7:00 M	—	— M	— M	<i>Clear</i>	72°	7:00 A.M.	1. This record shall be made at each station, office, or place from which the time of arrival, departure, or passing of trains is reported by telephone.
	M	M		M	M				2. Each operator and leverman shall enter time on and off duty in the space provided.
	M	M		M	M				
	M	M		M	M				

TRANSFER RECORD

TRAIN ORDERS TO BE DELIVERED

MESSAGES TO BE DELIVERED

OVERDUE TRAINS

TRAIN ORDER SIGNAL DISPLAYED

TRAIN ORDERS IN EFFECT

READ, UNDERSTOOD AND SIGNED

West WAR

3¹⁰ P. M.

AT W^o S — M

~~One~~
Closed account
Holiday

~~Abolished~~ 1918-9 23-60

Abolished

East WARD

STATION RECORD OF TRAIN MOVEMENTS (The Baltimore & Ohio R.R.)

~~C. T. 355-B REV~~

THE PENNSYLVANIA RAILROAD COMPANY.

REGION C. O. R. W.
Western B.O.

STATION *Summit, Ohio*

DATE

OPERATOR	ON DUTY	OFF DUTY	LEVERMAN	ON DUTY	OFF DUTY	WEATHER	Temp.	Time	INSTRUCTIONS
<i>J. Reed</i>	8:00 A.M.	5:00 P.M.		M	M	<i>Clear</i>	68°	8:00 A.M.	Temporary
	M	M		M	M	<i>Clear</i>	72°	5:00 P.M.	
	M	M		M	M				
	M	M		M	M				

TRANSFER RECORD

AT 5⁰⁰ P.M.

AT _____ M

AT _____ M

TRAIN ORDERS TO BE DELIVERED

Signals for No 1 and
No 2 set for automatic
operation

Office Closed at 5:00 Pm

W Reed

MESSAGES TO BE DELIVERED

OVERDUE TRAINS:

OVERDUE TRAINS

TRAIN ORDER SIGNAL DISPLAYED

TRAIN ORDERS IN EFFECT

READ, UNDERSTOOD AND SIGNED

— WAR

WARD

TRAIN	ENG.	Time Block Given	Outville		Summit		REMARKS	TRAIN	ENG.	Time Block Given	Re-NY		Time Block Received	Summit		REMARKS
			Time Departed	Trk	Time Block Received	Time Arrived	Trk	Time Departed	Trk	Time Arrived	Trk	Time Departed	Trk	Time Block Cleared	Outville	
CH																
TAMPR 21-J		805 KO 2	820 2	#	#			TAMPR 21-J		821	out 204					
BB- 162K		805 KO 2	820 2	#	#			BB- 162K		8147	IN 352	BB for night				
Local 6590		820 1	908 1	908 1	1045	Day 935-1037		Local 6590		1222	4					
BB 054409		207 1			216 1	239		BB 054409		347	2					

STATION RECORD OF TRAIN MOVEMENTS

© 2005 REED BUSINESS INFORMATION

Timareet Ohio RR Co.

REGION 13.9 YL. VWN.

STATION

DATE

4719

OPERATOR	ON DUTY	OFF DUTY	LEVERMAN	ON DUTY	OFF DUTY	WEATHER	Temp.	Time	INSTRUCTIONS
<i>S. Reed</i>	8 ^{AM}	5 ^{PM}		M	M	<i>Clear</i>	72°	8 ^{AM}	1. This record shall be made at each station, office, or place from which the time of arrival, departure, or passing of trains is reported by telephone.
	M	M		M	M	<i>Clear</i>	94°	5 ^{PM}	2. Each operator and leverman shall enter time on and off duty in the space provided.
	M	M		M	M				
	M	M		M	M				

TRANSFER RECORD

TRAIN ORDERS TO BE DELIVERED

MESSAGES TO BE DELIVERED

OVERDUE TRAINS

TRAIN ORDER SIGNAL DISPLAYED

TRAIN ORDERS IN EFFECT

READ, UNDERSTOOD AND SIGNED

AT _____ M

10

AT

M

5^{oo} Pm No 1 and No 2
tracks set to operate
automatically and office
closed for the night

Reed

AT _____ M

1

AT M

West - WAR

East. WARD

STATION RECORD OF TRAIN MOVEMENTS

The Baltimore & Ohio R.R.

REGION (4) DIVISION

STATION ✓

DAZÉE

C. T. 255 R. BEE

THE PENNSYLVANIA RAILROAD COMPANY

OPERATOR	ON DUTY	OFF DUTY	LEVERMAN	ON DUTY	OFF DUTY	WEATHER	Temp.	Time	INSTRUCTIONS
<i>P. Reed</i>	M	M		M	M	<i>clear</i>	<i>74°</i>	<i>8:00 AM</i>	<i>100% day</i>
	M	<i>5:00 PM</i>		M	M	<i>clear</i>	<i>96°</i>	<i>5:00 PM</i>	
	M	M		M	M				
	M	M		M	M				

TRANSFER RECORD

AT 5⁰⁰ P. M

AT _____ M

TRAIN ORDERS TO BE DELIVERED

MESSAGES TO BE DELIVERED

OVERDUE TRAINS:

TRAIN ORDER SIGNAL DISPLAYED

TRAIN ORDERS IN EFFECT:

READ, UNDERSTOOD AND SIGNED

West-WAR

✓ *Leucostethus* *leucostethus* (Linné)

East WARD

STATION RECORD OF TRAIN MOVEMENT

St. Louis, Baltimore & Ohio RR Co.

REGION Central

STATION

DATE

19 ~~66~~

C. T. SEE-BEY

OPERATOR	ON DUTY	OFF DUTY	LEVERMAN	ON DUTY	OFF DUTY	WEATHER	Temp.	Time	INSTRUCTIONS
<i>K. Reed</i>	8 ⁰⁰ A.M.	9 ⁰⁰ M		M	M	<i>Cloudy</i>	72°	8 A.M.	1. This record shall be made at each station, office, or place from which the time of arrival, departure, or passing of trains is reported by telephone.
	M	M		M	M	<i>Clear</i>	85°	5 P.M.	2. Each operator and leverman shall enter time on and off duty in the space provided.
	M	M		M	M				
	M	M		M	M				

TRANSFER RECORD

AT 5⁰⁰ P.M

AT M

AT M

TRAIN ORDERS TO BE DELIVERED

MESSAGES TO BE DELIVERED

OVERDUE TRAINS

TRAIN ORDER SIGNAL DISPLAYED

TRAIN ORDERS IN EFFECT

READ, UNDERSTOOD AND SIGNED

Patrick (On duty 8am 9-10-60)

West - WAI

East- WARD

Time Oct. 11

