

PENN CENTRAL COMPANY

3-69

Printed in U.S.A.

REGION

STATION

DATE _____

Western

North Judson

Aug. 1, 1976

TRANSFER RECORD

AT 7⁰⁰ AM

AT 3 PM

AT 11 PM

Hamlet

No. Jackson

Kankakee Branch

Shelby

no. Judson

AUG 1976

CT 355-A Rev. 3-69
Printed in U.S.A.

REGION

STATION

DATE _____

Western North Hudson Aug. 2, 1976

INSTRUCTIONS

1. This record shall be made at each station, office, or place from which the time of arrival, departure, or passing of trains is reported by telephone.
2. Each operator and leverman shall enter time on and off duty in the space provided.

SAFETY RULE 1004		AT 7 ⁰⁰ AM	AT 3 P.M.	AT 4 P.M.
TRAIN ORDERS TO BE DELIVERED	No. 102-209	No. 122-210	No. 122-210	No. 122-225
MESSAGES TO BE DELIVERED	None. 1 On Hook Opria.	None	None	None
OVERDUE TRAINS	None.	None	None	None
TRAIN ORDER SIGNAL DISPLAYED	East	East	East	East
TRAIN ORDERS IN EFFECT	No. 102-208-209	No. 122-210	No. 122-210	No. 122-225
READ, UNDERSTOOD AND SIGNED	R. B. Henry West WARD	W. Skille	W. Skille	F. J. Liedtke East WARD

[illegible]

STATION RECORD OF TRAIN MOVEMENTS

CT 353-A Rev. 3-69
Printed in U.S.A.

PENN CENTRAL COMPANY

REGION Western STATION North Judson DATE Aug. 3, 1976

Operator	On Duty	Off Duty	Leverman	On Duty	Off Duty	Weather	Temp	Time
<u>F. J. Liedtke</u>	<u>12am</u>	<u>7am</u>		<u>M</u>	<u>M</u>			
<u>R. L. Ford</u>	<u>7am</u>	<u>3P M</u>		<u>M</u>	<u>M</u>			
<u>RC Henry</u>	<u>3P M</u>	<u>11P M</u>	<u>B. S. J.</u>	<u>M</u>	<u>M</u>			
<u>Drasner</u>	<u>11P M</u>	<u>12PM</u>		<u>M</u>	<u>M</u>			

INSTRUCTIONS
1. This record shall be made at each station, office, or place from which the time of arrival, departure, or passing of trains is reported by telephone.
2. Each operator and leverman shall enter time on and off duty in the space provided.

TRANSFER RECORD

	AT <u>7⁰⁰am</u>	AT <u>3P M</u>	AT <u>11P.M.</u>
TRAIN ORDERS TO BE DELIVERED	<u>No. 101-208</u>	<u>No. 101-117-118-208-230</u>	<u>No. 101-234-244</u>
MESSAGES TO BE DELIVERED	<u>None. / On Hook Oprie.</u>	<u>None - On hook</u>	<u>None</u>
OVERDUE TRAINS	<u>None.</u>	<u>None</u>	<u>None</u>
TRAIN ORDER SIGNAL DISPLAYED	<u>East.</u>	<u>West</u>	<u>East</u>
TRAIN ORDERS IN EFFECT	<u>No. 101-208</u>	<u>No. 101-117-118-208-216-230</u>	<u>No. 101-234-242-244</u>
READ, UNDERSTOOD AND SIGNED	<u>R. L. Ford</u> <u>West</u> WARD	<u>RC Henry</u> <u>East</u> WARD	<u>Drasner</u>

Van				No. Judson				REMARKS		No. Judson				REMARKS		
TRAIN	ENG.	Time Block Given	Time Block Received	Time Arrived	Trk.	Time Departed	Trk.		TRAIN	ENG.	Time Block Given	Time Block Received	Time Arrived	Trk.	Time Departed	Trk.
L-45	7187	1001			X	1039	2	Eng No 1001	ULG-66230		355	1	1	432	1	40550
L-45	7187	1001			X	1039	2		NGC-26031		624	1	1	652	1	933
CK-1	7187	1001			X	406	3		CK-2 2706		1052	1	1	1112	1	1215
CK-3	2706	1001			X	1114	2		ABC 5406		1202	1	1	1215	1	1215
CK-3	2706	1059			X	1225	2		PBD 1		200	1	1	221	1	407
									Ld-1 7187		200	1	1	221	1	WVF
									CD 6 7187		487	1	1	412	1	520
									NYW 29 6803		487	1	1	412	1	520
									PBPA East on No 1		1043	1	1	412	1	520
									IC 2 3132		1043	1	1	412	1	520

CT 355-A Rev. 3-69
Printed in U.S.A.

REGION

STATION

DATE

WESTERN

NORTH SUDSON

FIG. 4, 1976

Operator	On Duty	Off Duty	Leverman	On Duty	Off Duty	Weather	Temp	Time	INSTRUCTIONS 1. This record shall be made at each station, office, or place from which the time of arrival, departure, or passing of trains is reported by telephone. 2. Each operator and leverman shall enter time on and off duty in the space provided.
<i>Drasner</i>	12 A M	7 A M		M	M				
<i>Drasner</i>	7 A M	3 P M		M	M				
<i>R. H. Denny</i>	3 P M	11 P M	<i>Boh</i>	M	M				
<i>Drasner</i>	11 P M	12 P M		M	M				

	AT 7 A M	AT 3 P M	AT 11 P M
TRAIN ORDERS TO BE DELIVERED	No 5. 105-208	No 105-208	No 105-141-224
MESSAGES TO BE DELIVERED	NONE	None	NONE
OVERDUE TRAINS	NONE	None	NONE
TRAIN ORDER SIGNAL DISPLAYED	WESTWARD	East	East
TRAIN ORDERS IN EFFECT	No 5. 105-208	No 105-208	No 105-141-224
READ, UNDERSTOOD AND SIGNED	H. L. Ford	R. B. Henry	Drasner
	WESTWARD		EASTWARD

[illegible]

CT 355-A Rev.

3-69

Printed in U.S.A.

PENN CENTRAL COMPANY

REGION

STATION

DATE _____

WESTERN

NORTH JUDSON

AUG. 5, 1974

INSTRUCTIONS

1. This record shall be made at each station, office, or place from which the time of arrival, departure, or passing of trains is reported by telephone.
2. Each operator and leverman shall enter time on and off duty in the space provided.

TRANSFER RECORD

WEST WARD

EAST WARD

on East end of Conkoken siding 9x38 (worn)
CR-4 2278 5/10H 20 1/4 E End Pass SF-3 8043 P/up.
#1 TRK. 6/16 KAN. SF3 8043 P/up.

W. END KKK SIDING 9/14 KAN. 3/10 AT ST. Pk. SE-1A and 1S
#2 TRK. 3/1 ELK. & WIDE LD. LOGAN

SHELBY NAJULSON

X-2 3627	1150 M	1245 M	101 M
1806 1837	M	324 M	440 M
1834 3182	314 M	440 M	514 M
XK2 6015	732 M	M	920 M

[illegible]

K84 3122 broke intake West end No 1 Trk Switch between
10th end 11th behind Eng's RSP 14502 loaded box and
P.L. 14502 empty 1000 P.L. 14502 - 11th end - 1000

CT 355-A Rev.

8-69

Printed in U.S.A.

PENN CENTRAL COMPANY

Western

No. Jackson

Aug. 6 1976

Operator	On Duty	Off Duty	Leverman	On Duty	Off Duty	Weather	Temp	Time	INSTRUCTIONS
R.B. Henry	12014 M	74 M	B.S.R.	M	M				1. This record shall be made at each station, office, or place from which the time of arrival, departure, or passing of trains is reported by telephone.
D. A. Ford	7a M	3P M		M	M				2. Each operator and leverman shall enter time on and off duty in the space provided.
G. Skibbe	3P M	11P M		M	M				
	11P M	12P M		M	M				

TRANSFER RECORD

	AT 7 ⁴⁵ M.	AT 3 ⁰⁰ M.	AT 11 ⁰⁰ M.
TRAIN ORDERS TO BE DELIVERED	No 105-205-206-210	No 210-110-132	None
MESSAGES TO BE DELIVERED	None	None	None
OVERDUE TRAINS	None	None	None
TRAIN ORDER SIGNAL DISPLAYED	East	East-West	None
TRAIN ORDERS IN EFFECT	No 105-204-205-206-210	No 210-110-132	None
READ, UNDERSTOOD AND SIGNED	H. L. T. for West	W. Skibbe	W. Skibbe
	WARD		WARD

TRAIN	ENG.	Time Block Given	Van		Time Block Received	To Jordon				Time Block Cleared	REMARKS	TRAIN	ENG.	Time Block Given	Lacrosse		Time Block Received	To Jordon				Time Block Cleared	REMARKS
			Time Departed	Trk.		Time Arrived	Trk.	Time Departed	Trk.						Time Departed	Trk.		Time Arrived	Trk.	Time Departed	Trk.		
SE-4	2287		420	2	N.O.	505						PKR East on X	1	1	1	1	1	251	1	1	127	PRD	
IC-1	2747	0022	407	1		842	1	WVE	1	876		SE-4	2287	0022	407	1	1	619	1	1	653		
SE-5	7112	856	407	1		1002	X	1027	2	1047		CK-2	6075		1127	1	1	133	1	1	227	HO	
CK-2	8023	1009	410	1			1	WVE	1	126		CO-8	780		149	1	1	274	1	1	335	HO	
SE-1	6062	0022	740	1	0025		1	843	1	905		K-6	7112		225	1	1	258	1	1	439	HO (8X3 logs)	
												CTC-2	6014		576	1	1	550	1	1	818		
												PKR on Eastward	1				1	657	1	1	845	PRD	

CT 355-A Rev. 3-69
Printed in U.S.A.

REGION

STATION

DATE _____

WESTERN

NORTH JUDSON

Aug. 7, 1976

Operator	On Duty	Off Duty	Leverman	On Duty	Off Duty	Weather	Temp	Time	INSTRUCTIONS
<i>Grasby</i>	12 AM	7 AM		M	M				1. This record shall be made at each station, office, or place from which the time of arrival, departure, or passing of trains is reported by telephone. 2. Each operator and leverman shall enter time on and off duty in the space provided.
<i>Ford</i>	7 AM	3 P M		M	M				
<i>W. P. Pitts</i>	3 P M	11 P M		M	M				
<i>W. P. Pitts</i>	11 P M	12 P M		M	M				

SR 1105-G

AT 7 AM

AT 3 P M

AT 11 P M

TRAIN ORDERS TO BE DELIVERED

NO. 215

No 215

None

MESSAGES TO BE DELIVERED

NONE

On hook

on hoop

OVERDUE TRAINS

WONE

None

Name _____

TRAIN ORDER SIGNAL DISPLAYED

EASTWARD

East

None

TRAIN ORDERS IN EFFECT

NO. 215

No. 215-2/15

Nome

READ, UNDERSTOOD AND SIGNED

K. L. Ford

[Handwritten signature]

F. L. Luedtke

WEST WARD

EAST WARD

[illegible]

RS 7837 trail up on west end of ridge 11 x 15 km. Kake / P up DC7 R6087

STATION RECORD OF TRAIN MOVEMENTS

CT 355-A Rev.

3-69

Printed in U.S.A.

PENN CENTRAL COMPANY

REGION

STATION

DATE

Western

North Judson

Aug. 8, 1976

Operator	On Duty	Off Duty	Leverman	On Duty	Off Duty	Weather	Temp	Time
F. J. Liedtke	12am	7am		M	M			
R. K. Nunn	7am	3pm	R. K. L.	M	M			
G. Kibbe	3pm	11pm		M	M			
F. J. Liedtke	11pm	12pm		M	M			

INSTRUCTIONS

1. This record shall be made at each station, office, or place from which the time of arrival, departure, or passing of trains is reported by telephone.
2. Each operator and leverman shall enter time on and off duty in the space provided.

TRANSFER RECORD

SAFETY RULE - 1127		AT 7 ⁰⁰ AM	AT 3 P. M.	AT 11 P. M.
TRAIN ORDERS TO BE DELIVERED	No. 101	No. 101 - 212 - 213	No. 101	
MESSAGES TO BE DELIVERED	1 Cts Westward Trains originating		on hook	
OVERDUE TRAINS	None.		None	
TRAIN ORDER SIGNAL DISPLAYED	None.		None	
TRAIN ORDERS IN EFFECT	No. 101	No. 101 - 211 - 212 - 213	No. 101	
READ, UNDERSTOOD AND SIGNED	R. K. Nunn.	G. Kibbe	F. J. Liedtke	
	Westward		Eastward	

TRAIN	ENG.	Time Block Given	Time Block Received	REMARKS	TRAIN	ENG.	Time Block Given	Time Block Received	REMARKS
Van					Koute Lalrose				
		Time Departed	Trk.				Time Departed	Trk.	
201	1	627	2	M.S. 257	1	129	1	301	PBDR.
627	2	735	2	S.C. 805	X	422	1	505	
735	2	847	1	S.C. 847	X	728	1	900	5/6 1/10, 1/15 3/4
847	1	920	1	X 359	2	944	1	959	
920	1	947	2	X 245	2	1055	1	1057	PBDR
947	2	953	1	X 742	2	1044	1	1112	106
953	1	1041	2	X 350	2	1053	1	359	PBDR
1041	2			Thornhope.		307	1	505	245
						434	1	533	
								558	PBDR

CT 355-A Rev. 3-69
Printed in U.S.A.

REGION

STATION

DATE _____

Western

North Judson

Aug. 9, 1976

INSTRUCTIONS

1. This record shall be made at each station, office, or place from which the time of arrival, departure, or passing of trains is reported by telephone.
2. Each operator and leverman shall enter time on and off duty in the space provided.

SAFETY RULE-1112-B		AT 7 ⁰⁰ A.M.	AT 3 P.M.	AT 11 P.M.
TRAIN ORDERS TO BE DELIVERED	No. 101-202-205	No. 101-205	No. 233	
MESSAGES TO BE DELIVERED	1-CXE Westward Trains originating	1 Message west	on book	
OVERDUE TRAINS	None.	None East	None	
TRAIN ORDER SIGNAL DISPLAYED	East	None East	East	
TRAIN ORDERS IN EFFECT	No. 101-201-202-205	No. 101-205	No. 233	
READ, UNDERSTOOD AND SIGNED	R. B. Henry	R. B. Henry	F. J. Liedtke	
	West WARD		East WARD	

TRAIN	ENG.	Time Block Given	Van Time Block Received Trk.	No. Judson Time Arrived Trk.	Time Departed Trk.	Remarks
CK-3A 3154	M 330	H.O. 350	1	517 X	613 2	80 1/4 KKK, 2 3/4 SFE
CIC-1 7894		528	2	H.O. 617	2 7-0 3/4	Thornhope.
CIC-1 7894	M 220	H.O. 620	1	X 714	2 751	
PB A 220	X 2			2 859	2 1025	
KRC 3066	Campbell			2 901	2 1025	
D 5 5675			1	X 1041	2 1101	
SF 1-3 3624		612 M		M 738	M	
SF 1-2 2276		751 m		828 m	850 m	
BET 3649		1238 m		118 m	450 m	
NDA-1 3105		301 M		340 M	500 M	
KOS 2303				M	532 M	
UNW 31 8923		603 M		11 630 M	770	Chand NIBRO

CT 355-A Rev. 3-69
Printed in U.S.A.

REGION

STATION

DATE _____

Western	North Judson	Aug. 10, 1976
---------	--------------	---------------

Operator	On Duty	Off Duty	Leverman	On Duty	Off Duty	Weather	Temp	Time
F. J. Liedtke	12am	7am		M	M			
H. L. Ford	7am	3P M		M	M			
R. G. Barry	3P M	11P. M	Be. L.	M	M			
L. J. L. L.	11P M	12P M		M	M			

INSTRUCTIONS

1. This record shall be made at each station, office, or place from which the time of arrival, departure, or passing of trains is reported by telephone.
2. Each operator and leverman shall enter time on and off duty in the space provided.

SAFETY RULE-1052-I		AT 7 ⁰⁰ AM	AT 3 P M	AT 11 P.M.
TRAIN ORDERS TO BE DELIVERED	No. 233	No. 210	No. 628-246	
MESSAGES TO BE DELIVERED	1-CtE Westward Trains originating	on hook	on hook	
OVERDUE TRAINS	None.	None	None	
TRAIN ORDER SIGNAL DISPLAYED	East	East	East	
TRAIN ORDERS IN EFFECT	No. 233	No. 210	No. 628-245-2x6	
READ, UNDERSTOOD AND SIGNED	R. L. Ford	R. L. Ford	R. L. Ford	
	West WARD		East WARD	

[illegible]

CT 355-A Rev. 3-69
Printed in U.S.A.

REGION

STATION

DATE

WESTERN

NORTH JUDSON AUG. 11, 1970

INSTRUCTIONS

1. This record shall be made at each station, office, or place from which the time of arrival, departure, or passing of trains is reported by telephone.
2. Each operator and leverman shall enter time on and off duty in the space provided.

SR 1156-E

WEST WARD

EAST WARD

[illegible]

CT 355-A Rev. 3-69
Printed in U.S.A.

REGION

STATION

DATE _____

WESTERN

NORTH JUDSON

AUG. 12, 1974

Operator	On Duty	Off Duty	Leverman	On Duty	Off Duty	Weather	Temp	Time
<i>W. J. Ford</i>	12 A M	7 A M	<i>Paul E. Vento</i>	1201 A M	700 A M			
<i>W. J. Ford</i>	7 A M	3 P M		M	M			
<i>W. J. Ford</i>	3 P M	11 P M		M	M			
<i>W. J. Ford</i>	11 P M	12 P M	<i>P. E. Vento</i>	1100 P M	1159 P M			

INSTRUCTIONS

1. This record shall be made at each station, office, or place from which the time of arrival, departure, or passing of trains is reported by telephone.
2. Each operator and leverman shall enter time on and off duty in the space provided.

	AT 7 A M	AT 3 P M	AT 11 P M
TRAIN ORDERS TO BE DELIVERED	NO 5. 206-628	No 206-628-219-222	No 628
MESSAGES TO BE DELIVERED	ON HOOK	On hook	on hook
OVERDUE TRAINS	NONE	None	None
TRAIN ORDER SIGNAL DISPLAYED	EASTWARD	East	East
TRAIN ORDERS IN EFFECT	NO 5. 206-628-105	No 206-628-209-219-222.	No 628
READ, UNDERSTOOD AND SIGNED	M. L. Ford	L. Skibbe	L. B. Perry
	WEST WARD		EAST WARD

[illegible]

CT 355-A Rev. 3-69
Printed in U.S.A.

REGION

Western

STATION

North Indsian Aug 13 1976

DATE _____

Aug 13 1976

Operator	On Duty	Off Duty	Leverman	On Duty	Off Duty	Weather	Temp	Time
RBS Henry	1204 M	704 M	R & Ventr	1201 A M	700 A M	Posting		
R. L. Ford	7a M	3P M		M	M			
GO Keith	3P M	11P M		M	M			
L. L. L...	11P M	12P M		M	M			

INSTRUCTIONS

1. This record shall be made at each station, office, or place from which the time of arrival, departure, or passing of trains is reported by telephone.
2. Each operator and leverman shall enter time on and off duty in the space provided.

	AT 700A M	AT 3P M	AT 11P M
TRAIN ORDERS TO BE DELIVERED	No 628-209-204	No-209-628-124-125	No's. 130 - 628
MESSAGES TO BE DELIVERED	1	On hook	on hook
OVERDUE TRAINS	None	None	None
TRAIN ORDER SIGNAL DISPLAYED	East	East	East
TRAIN ORDERS IN EFFECT	No 628-209-204	No-209-628-124-125	No 130 - 628
READ, UNDERSTOOD AND SIGNED	H. Linton	[Signature]	[Signature]
	West WARD		East WARD

[illegible]

CT 355-A Rev. 3-69
Printed in U.S.A.

PENN CENTRAL COMPANY

REGION

STATION

DATE _____

WESTERN

NORTH JUDSON

AUG. 13, 1970

Operator	On Duty	Off Duty	Leverman	On Duty	Off Duty	Weather	Temp	Time	INSTRUCTIONS
<i>Drasys</i>	12 A M	7 A M	<i>P. E. Venter</i>	M	M				1. This record shall be made at each station, office, or place from which the time of arrival, departure, or passing of trains is reported by telephone. 2. Each operator and leverman shall enter time on and off duty in the space provided.
<i>R. L. Ford</i>	7 A M	3 P M		4 A M	3 P M				
<i>G. E. Kirby</i>	3 P M	11 P M		M	M				
<i>F. J. Liettker</i>	11 P M	12 P M		M	M				

TRANSFER RECORD

	AT 7 AM	AT 3 PM	AT 11 PM
TRAIN ORDERS TO BE DELIVERED	NOS. 101-202-209-628	628-101	Nos 628-224-226 = 101-142
MESSAGES TO BE DELIVERED	ON HOOK	On hook	On hook
OVERDUE TRAINS	NONE	None	None
TRAIN ORDER SIGNAL DISPLAYED	EASTWARD (PC) (KKK)	Eastward (PC) (KKK)	Eastward
TRAIN ORDERS IN EFFECT	NOS. 101-201-202-209-628	Same as above	Nos. 628-223-224-226 = 101-142
READ, UNDERSTOOD AND SIGNED	A. L. Ford	J. J. Liddy	J. J. Liddy
	WEST WARD		EAST WARD

[illegible]

CT 355-A Rev. 1-69 PRINTED IN USA MU

PENN CENTRAL TRANSPORTATION CO.

Western

North Judson

Aug. 15 197

INSTRUCTIONS

1. This record shall be made at each station, office, or place from which the time of arrival, departure, or passing of trains is reported by telephone.
2. Each operator and leverman shall enter time on and off duty in the space provided.

SAFETY RULE-1205-D		AT 7 ⁰⁰ AM	AT 3 P M	AT 11 P M
TRAIN ORDERS TO BE DELIVERED	No. 101-209-628	No. 628-101-116	No. 101-628-225	
MESSAGES TO BE DELIVERED	1 msg-Cte Westward Train originating	On Hook	on Hook	
OVERDUE TRAINS	None.	None	None	
TRAIN ORDER SIGNAL DISPLAYED	East.	East	East	
TRAIN ORDERS IN EFFECT	No. 101-208-209-628	No. 628-101-116	No. 101-628-224-225	
READ, UNDERSTOOD AND SIGNED	<i>J. Ford</i>	<i>G. Skille</i>	<i>F. J. Liedtke</i>	
	West WARD		East WARD	

CK3A2965 Spout on West end KKK siding - BB# 64406

DATE _____

Aug. 16, 1976

INSTRUCTIONS

1. This record shall be made at each station, office, or place from which the time of arrival, departure, or passing of trains is reported by telephone.
2. Each operator and leerman shall enter time on and off duty in the space provided.

SAFETY RULE-1111-B

SAFETY RULE-1111-B		AT 7 ⁰⁰ AM	AT 3 P.M.	AT 11 P.M.
TRAIN ORDERS TO BE DELIVERED	No. 628-101-207	No 628-217-101	No. 628-101	
MESSAGES TO BE DELIVERED	On Hook.	on Hook	On Hook.	
OVERDUE TRAINS	None.	None	None	
TRAIN ORDER SIGNAL DISPLAYED	East.	East KB-PC	East	
TRAIN ORDERS IN EFFECT	No. 628-101-207	No 628-217-101	No. 628	
READ, UNDERSTOOD AND SIGNED	R. B. Henry	L. J. Kibbe	F. J. Liedtke	
	West WARD		East WARD	

[illegible]

CT 355-A Rev. 1-69 PRINTED IN USA NU

REGION

STATION

DATE _____

Western

North Judson Aug. 17, 1970

INSTRUCTIONS

1. This record shall be made at each station, office, or place from which the time of arrival, departure, or passing of trains is reported by telephone.
2. Each operator and leverman shall enter time on and off duty in the space provided.

TRANSFER RECORD

AT 7⁰⁰ AM

AT 300 P M

AT 1100 M

TRAIN ORDERS TO BE DELIVERED	No. 628-206-101	No-628-206-101	101-628
MESSAGES TO BE DELIVERED	On Hook.	On hook	On Hook
OVERDUE TRAINS	None.	None	none
TRAIN ORDER SIGNAL DISPLAYED	East	East	East
TRAIN ORDERS IN EFFECT	No. 628-206-101	No-628-206-101	Long as above
READ, UNDERSTOOD AND SIGNED	R. L. Ford	per	James
	West		East

[illegible]

Called Swish	Not Home	1000PM	Called Mendenhall	1010 PM OK FLY FLASHERS N. JOHNSON
--------------	----------	--------	-------------------	------------------------------------

DATE _____

NORTH JUDSON AUG. 18, 1976

INSTRUCTIONS

1. This record shall be made at each station, office, or place from which the time of arrival, departure, or passing of trains is reported by telephone.
2. Each operator and leverman shall enter time on and off duty in the space provided.

TRANSFER RECORD

WEST WARD

#	TRUCK	WOFOR	SLIPSHEWANNA	(EUKHAK)
---	-------	-------	--------------	----------

SIDING 16-25 FOR AVON

#1 TRK. $\frac{4}{6}$ KAA $\frac{4}{4}$ ATSE SF-2 360 P/yr.

E. END KKK SIDING 4.5 CARS AROUND LK 1549 1/4

STANKERLE BRANCH

SHELVY

NO. JUDSON

3/045 AVONS

Крох

LD-16	HIT EDE	3:40 PM	TOLD HIM TO STOP AND INSPECT HIS TRAIN	OR TRAIN 3:50
LD-4	6:51 PM	HIT EDE	6:10 PM	6:20

DATE _____

NORTH JUDSON AUG. 19, 1976

INSTRUCTIONS

1. This record shall be made at each station, office, or place from which the time of arrival, departure, or passing of trains is reported by telephone.
2. Each operator and leverman shall enter time on and off duty in the space provided.

SR 1010-D

AT 7 AM

AT 3 P M

AT 11 P M

NOS. 214-628

ON HOOK

NONE

EASTWARD

Nos. 214-628

17 and

WEST WARD

EAST WARD

[illegible]

CT 355-A Rev. 1-69 PRINTED IN USA MU

PENN CENTRAL TRANSPORTATION CO.

REGION

STATION

DATE

Western

No. Judson

Aug-2019

Operator	On Duty	Off Duty	Leverman	On Duty	Off Duty	Weather	Temp.	Time	INSTRUCTIONS
R. K. Harvey	1201 A.M.	7 A.M.	E. S. S.	M	M				1. This record shall be made at each station, office, or place from which the time of arrival, departure, or passing of trains is reported by telephone.
R. L. Ford	7 A.M.	3 P.M.		M	M				2. Each operator and leverman shall enter time on and off duty in the space provided.
G. D. Kibbe	3 P.M.	11 P.M.		M	M				
	M	M		M	M				

TRANSFER RECORD

	AT 74 M.	AT 3 P M	AT 11 P M
TRAIN ORDERS TO BE DELIVERED	No 628-212-208	No's 628-212-124	No. 647
MESSAGES TO BE DELIVERED	on hook	On hook	on hook
OVERDUE TRAINS	None	None	None
TRAIN ORDER SIGNAL DISPLAYED	East	East + West	East
TRAIN ORDERS IN EFFECT	No 628-212-207-208	No's 628-212-124	No. 647
READ, UNDERSTOOD AND SIGNED	H. J. Ford	G. Skibbe	James
	West WARD		East WARD

[illegible]

DATE _____

Aug. 21, 1970

INSTRUCTIONS

1. This record shall be made at each station, office, or place from which the time of arrival, departure, or passing of trains is reported by telephone.
2. Each operator and leverman shall enter time on and off duty in the space provided.

AT 11 P M

WEST WARD

[illegible]

CT 355-A Rev. 1-69 PRINTED IN USA MU

REGION

STATION

DATE _____

Western

North Judson

Aug. 22, 1970

INSTRUCTIONS

1. This record shall be made at each station, office, or place from which the time of arrival, departure, or passing of trains is reported by telephone.
2. Each operator and leverman shall enter time on and off duty in the space provided.

SAFETY RULE-1155-C

AT 7⁰⁰ am

AT 3 P.M.

AT 11 P M

TRAIN ORDERS TO BE DELIVERED	No. 647	No. 647	No. 647-219-222
MESSAGES TO BE DELIVERED	On Hook.	on hook	on Hook
OVERDUE TRAINS	None.	None	None
TRAIN ORDER SIGNAL DISPLAYED	East	East	East
TRAIN ORDERS IN EFFECT	No. 647	No. 647	No. 647-218-219-222
READ, UNDERSTOOD AND SIGNED	R. B. Henry	G. O. Miller	F. J. Liedtke
	West WARD	East	East WARD

[illegible]

CT 355-A Rev. 1-69 PRINTED IN USA MU

REGION

STATION

DATE _____

Western

North Judson

Aug. 23, 1978

INSTRUCTIONS

1. This record shall be made at each station, office, or place from which the time of arrival, departure, or passing of trains is reported by telephone.
2. Each operator and leverman shall enter time on and off duty in the space provided.

TRANSFER RECORD

SAFETY RULE = 1203-C

AT 7⁰⁰ AM

AT 3 PM

AT 11 P M

TRAIN ORDERS TO BE DELIVERED	No. 647	No. 647-206-219-120	No. 647-650
MESSAGES TO BE DELIVERED	On Hook.	on Hook	on Hook
OVERDUE TRAINS	None.	None	None
TRAIN ORDER SIGNAL DISPLAYED	East	East	East
TRAIN ORDERS IN EFFECT	No. 647-203	No. 647-203-206-219-120	No. 647-650
READ, UNDERSTOOD AND SIGNED	R. B. Henry.	G. Kille	F. J. Liedtke
	West		East
	WARD		WARD

[illegible]

	Hamlet	No. Judson	Kankakee Branch	Shelby	No. Judson
SF-1 8149	126 M	153 M 215 M	3/4 pig 3237 on 1/2 Cn KK 216335	420 M	M 631 M
SF1A 6500 (3237)	415 M	459 M 555 M	1/2 pig 3237 & 30 can KK 63110	504 M	700 M 740
SF-3 3632	625 M	710 M 742 M	1/2 3/8 KKK, 1/4 ATSE HM 22207	844 M	M 949 M
NH 2324	1008 M	1044 M 1142 M	Pup 3221		
125 3153		M 952 M			

PENN CENTRAL TRANSPORTATION CO.

DATE _____

Aug. 24, 1976

INSTRUCTIONS

1. This record shall be made at each station, office, or place from which the time of arrival, departure, or passing of trains is reported by telephone.
2. Each operator and leverman shall enter time on and off duty in the space provided.

SAFETY RULE - 1115

AT 3 P M

AT 11 P.M.

No. 647-650-216
On Hook.
None.
East.
No. 647-650-216
At Lrd End
West WARD

No's 647-650-216-121
On hook
None
East-West
No's 647-650-216-121
R.B. Henry

No 647-650
on Hook
Stone
East
No 647-650
Draught
East

West WARD

WARD

[illegible]

DATE _____

AUG. 25, 1970

INSTRUCTIONS

1. This record shall be made at each station, office, or place from which the time of arrival, departure, or passing of trains is reported by telephone.
2. Each operator and leverman shall enter time on and off duty in the space provided.

SR 1015

	AT 7 A M	AT 3 P M	AT 11 P M
SR 1015 TRAIN ORDERS TO BE DELIVERED	NOS. 647-650-204	No's-647-650-204	No. 647-650
MESSAGES TO BE DELIVERED	ON HOOK	On hook	on hook
OVERDUE TRAINS	NONE	None	None
TRAIN ORDER SIGNAL DISPLAYED	EASTWARD	East	East
TRAIN ORDERS IN EFFECT	NOS. 647-650-204	No's-647-650-204	No 647-650-132
READ, UNDERSTOOD AND SIGNED	R. J. [Signature]	R. B. Henry	[Signature]
	WEST WARD		EAST WARD

[illegible]

CT 355-A Rev. 1-69 PRINTED IN USA MU

REGION

STATION

DATE _____

Western

No. Judson

Aug. 27 1972

Operator	On Duty	Off Duty	Leverman	On Duty	Off Duty	Weather	Temp.	Time	INSTRUCTIONS
R.B. Henry	12d M	7d M	R.B. Henry	M	M				1. This record shall be made at each station, office, or place from which the time of arrival, departure, or passing of trains is reported by telephone.
H. L. Ford	7a M	3p M		M	M				2. Each operator and leverman shall enter time on and off duty in the space provided.
W. L. B. B. B.	3p M	11p M		M	M				
W. L. B. B. B.	11p M	12p M		M	M				

TRANSFER RECORD

	AT 7 A.M.	AT 3 P.M.	AT 11 P.M.
TRAIN ORDERS TO BE DELIVERED	None	No-654-219-128	No-107-654-149-150
MESSAGES TO BE DELIVERED	On Hook	On hook	On Hook
OVERDUE TRAINS	None	None	None
TRAIN ORDER SIGNAL DISPLAYED	East	East	East
TRAIN ORDERS IN EFFECT	None	No-654-210-219-128	No-107-654-149-150
READ, UNDERSTOOD AND SIGNED	K. L. Ford	G. Kible	G. Kible
	WARD	WARD	WARD

[illegible]

STATION RECORD OF TRAIN MOVEMENTS						REGION	STATION	DATE
CT 355-A Rev. 1-69 PRINTED IN USA MU						PENN CENTRAL TRANSPORTATION CO.		WESTERN NORTH JUDSON AUG. 28, 1970
Operator	On Duty	Off Duty	Leverman	On Duty	Off Duty	Weather	Temp.	Time
<i>F. J. Liedtke</i>	12 AM	7 AM		M	M			
<i>R. L. Ford</i>	7 AM	3 PM		M	M			
<i>R. D. Kibbe</i>	3 PM	11 PM		M	M			
<i>F. J. Liedtke</i>	11 PM	12 PM		M	M			

INSTRUCTIONS
 1. This record shall be made at each station, office, or place from which the time of arrival, departure, or passing of trains is reported by telephone.
 2. Each operator and leverman shall enter time on and off duty in the space provided.

TRANSFER RECORD			
	AT 7 AM	AT 3 PM	AT 11 PM
TRAIN ORDERS TO BE DELIVERED	NOS. 105-207-654	No-654	No 654-105
MESSAGES TO BE DELIVERED	ON HOOK	On Hook	On Hook
OVERDUE TRAINS	NONE	None	None
TRAIN ORDER SIGNAL DISPLAYED	EASTWARD	East	East
TRAIN ORDERS IN EFFECT	NOS. 105-206-207-654	No-654	No 654-105
READ, UNDERSTOOD AND SIGNED	<i>R. L. Ford</i>	<i>R. D. Kibbe</i>	<i>F. J. Liedtke</i>
	WESTWARD		EASTWARD

TRAIN	ENG.	Time Block Given	VAN		Time Block Received	NO. JUDSON				REMARKS	TRAIN	ENG.	Time Block Given	ACROSSE		Time Block Received	NO. JUDSON				REMARKS
			Time Departed	Trk.		Time Arrived	Trk.	Time Departed	Trk.					Time Arrived	Trk.		Time Departed	Trk.	Time Arrived	Trk.	
CK-3 6102	621	655	1			1	WYE	1	949		002 3216	329	1			1	402	1	537		
SW-5 6538	741	741	2			2	SC	2	931		PBDA EAST ON 1001 TRK.										
SV-5 6538	947	947	1			1	MS	1	1020		CK-2 2333	1058	1			1	1119	1	1249		
CIC-1 3087	930	930	2			2	SC	2	1230		LITE 6538	MS	1			1	1129	1	1247		
CIC-1 3087	1219	1219	1			1	WYE	1	146		COB 8043	709	1			1	728	1	923		
3-0 #1 KKK 6x23 Avons on No 1001 No END KKK SIDING 17/3 ATSF SF-3 P/4p 3-0 #1 KKK 6x23 Avons on No 1001 No END KKK SIDING 17/3 ATSF SF-3 P/4p																					
HAMLET DC-7 3215 SE-1 6051 CK-3 1825 SE-1 2392 CK-3 6102 MDH 7965 CIC-1 3087 NO. JUDSON SK 54 M 719 M 521 M 810 M 748 M M 937 M M 1001 M M 1113 M M 148 M P/4p S/4p STARKLEE BRANCH HM-2 7831 KN-2 3006 SHILBY 441 M 571 M NO. JUDSON 606 M 536 M 606 M 636 M 6-23 Avons																					

CT-355-A Rev. 1-69 PRINTED IN USA MU

REGION

STATION

DATE _____

Western

North Judson

Aug. 29, 1976

INSTRUCTIONS

1. This record shall be made at each station, office, or place from which the time of arrival, departure, or passing of trains is reported by telephone.
2. Each operator and leverman shall enter time on and off duty in the space provided.

TRANSFER RECORD

	AT 7 ⁰⁰ AM	AT 3 P.M.	AT 11 P.M.
SAFETY RULE-1109			
TRAIN ORDERS TO BE DELIVERED	No. 654-104	No 654	No 104-654
MESSAGES TO BE DELIVERED	On Hook.	None	On Hook
OVERDUE TRAINS	None.	None	None
TRAIN ORDER SIGNAL DISPLAYED	East.	East	East
TRAIN ORDERS IN EFFECT	No. 654-104	No 654	No 104-654
READ, UNDERSTOOD AND SIGNED	R.B. Murray	G. Skibbe	F.J. Liedtke
	West WARD		West WARD

[illegible]

DATE _____

Western North Hudson Aug. 30, 1976

INSTRUCTIONS

1. This record shall be made at each station, office, or place from which the time of arrival, departure, or passing of trains is reported by telephone.
2. Each operator and leverman shall enter time on and off duty in the space provided.

SECURITY RULE-1202-D		AT 7 ⁰⁰ AM	AT 3 P. M.	AT 11 P. M.
TRAIN ORDERS TO BE DELIVERED	No. 654-106-110	No 654	No. 654-106	
MESSAGES TO BE DELIVERED	On Hook.		On Hook	
OVERDUE TRAINS	None.		None	
TRAIN ORDER SIGNAL DISPLAYED	East and West		East	
TRAIN ORDERS IN EFFECT	No. 654-106-110	No 207-121-122	No 654-106	
READ, UNDERSTOOD AND SIGNED	R. B. Henry West	G. Kibbe	F. J. Liedtke East	

[illegible]