

SOUTHERN DIVISION
CLIC BULLETIN No. 7



CAR

LOCATION

IDENTITY

CODES

INSTRUCTIONS - MAPS

OAKDALE DISTRICT

REVISED: NOV. 1, 1983

CLIC INSTRUCTIONS

=====

THIS BOOKLET CONTAINS INSTRUCTIONS AND MAPS FOR THE CAR LOCATION IDENTITY CODE (CLIC) AND PROCEDURES GOVERNING THE WORK ORDER DOCUMENT SYSTEM.

MAPS ARE NOT DRAWN TO SCALE AND ARE TO BE USED ONLY AS A GUIDE TO LOCATING CUSTOMER AND YARD TRACKS AND THE NUMBERS ASSIGNED TO THEM.

THE GEOGRAPHICAL AREA COVERED IN THIS BOOKLET IS DIVIDED INTO ZONES. EACH ZONE HAS DESIGNATED TRACKS AND/OR INDUSTRIES WITHIN ITS BOUNDARY.

A CLIC NUMBER WILL CONSIST OF SIX DIGITS. THE FIRST TWO DIGITS DESIGNATE THE ZONE, THE SECOND TWO DIGITS INDICATE THE TRACK NUMBER WITHIN THE ZONE; THE LAST TWO DIGITS REPRESENT THE ACTUAL SPOT ALONG THE TRACK.

THE COMBINATION OF THE ZONE-TRACK-SPOT NUMBER IS KNOWN AS THE 'CAR LOCATION IDENTITY CODE' (CLIC).

THIS 'CLIC' NUMBER WILL BE USED FOR SWITCHING AND REPORTING PURPOSES RATHER THAN THE INDUSTRY OR TRACK NAME.

** EXAMPLE OF CLIC NUMBER **

16 09 05

/ / /

/ / /

/ / /

/ / /

/ / /

/ / /

/ / /

/ / /

/ / /

/ / /

/ / /

/ / /

/ / /

/ / /

/ / /

/ / /

/ / /

/ / /

/ / /

/ / /

/ / /

/ / /

/ / /

/ / /

/ / /

/ / /

/ / /

/ / /

/ / /

SPOT NUMBER

TRACK NUMBER

ZONE NUMBER

ALL SWITCH TARGETS OR STANDS HAVE BEEN PAINTED WITH A COMBINATION OF THE ZONE AND TRACK NUMBER.

SPOT NUMBERS HAVE BEEN PAINTED ON DOORS, DOCKS, BUILDINGS, GATES, ETC., WHEREVER POSSIBLE.

WORK ORDER DOCUMENT

=====

ANY WRITTEN OR VERBAL INSTRUCTIONS ISSUED TO YARD OR ROAD CREWS REQUIRING WORK TO BE PERFORMED DURING THEIR TOUR OF DUTY WILL CONSTITUTE A WORK ORDER.

NOTE: EXCEPTIONS TO WRITTEN WORK ORDER MUST BE NOTED ON THE WORK ORDERS ACCORDING TO CURRENT INSTRUCTIONS; CARS HANDLED ON VERBAL WORK ORDERS MUST BE REPORTED ON THE PRESCRIBED FORM.

CONDUCTORS AND ENGINE FOREMAN WILL BE FURNISHED WORK ORDERS DURING THEIR TOUR OF DUTY.

THIS DOCUMENT WILL SPECIFY THE CARS TO BE PICKED-UP OR SET-OUT AT VARIOUS STATIONS, INDUSTRIES, OR INTERCHANGE TRACKS SERVICED BY THE TRAIN OR SWITCH JOB.

CERTAIN INFORMATION (DESCRIBED BELOW) MUST BE RECORDED ON THE WORK ORDER DOCUMENT BY THE CONDUCTOR OR ENGINE FOREMAN. PRIOR TO TURNING IN THE DOCUMENT AT THE DESIGNATED REPORTING STATION, IT MUST BE DATED AND SIGNED-- EVEN IF NO WORK WAS ACCOMPLISHED. THIS IS NECESSARY TO COMPLY WITH THE SWITCHING AND DEMURRAGE TARIFFS AS WELL AS OTHER RULES AND REGULATIONS.

CONDUCTORS AND ENGINE FOREMAN MUST SHOW ON WORK ORDER CARS HANDLED TIME AND DATE WORK PERFORMED CLIC NUMBER TAKEN FROM, CLIC NUMBER LEFT AND THE APPROPRIATE CODE AS LISTED BELOW:

BO - BAD ORDER
ND - WORK INDICATED NOT DONE (STATE REASON)
NIT - CAR NOT IN TRAIN, OR NOT ON TRACK
OTCC - CAR ON TRACK, CARRIERS CONVENIENCE
OTNP - CAR ON TRACK, BUT NOT PLACED (STATE REASON)
PULL - CAR PULLED, TIME AND DATE
SPOT - CAR SPOTTED, TIME AND DATE

CONDUCTOR/ENGINE FOREMAN MUST MAKE A NOTATION ON WORK ORDER OF ANY EXCEPTIONS TAKEN, SUCH AS NO CAR, CAR NOT ON LIST, CAR OUT OF LINE, CAR IS HAZARDOUS, EXCESS DIMENSION (WHEN INFORMATION IS NOT SO INDICATED ON WORK ORDER), CAR IS CARDED REAR OR HEAD END MOVEMENT ONLY, OR ANY OTHER EXCEPTIONS NOTED.

IF SWITCHING IS PERFORMED WITHOUT A WORK ORDER, THE CONDUCTOR OR ENGINE FOREMAN MUST COMPLETE THE PRESCRIBED FORM SHOWING ALL THE INFORMATION REQUIRED ABOVE AND TURN IT IN AT THE DESIGNATED REPORTING STATION.

IF AN INDUSTRY REQUEST SERVICE NOT SHOWN ON THE WORK ORDER, CONDUCTOR/ENGINE FOREMAN SHOULD OBTAIN SUCH REQUEST IN WRITING. THIS REQUEST IS TO BE TURNED IN WITH WORK ORDER. IF UNABLE TO OBTAIN REQUEST IN WRITING, CONDUCTOR/ENGINE FOREMAN SHOULD RECORD ON WORK ORDER THE NAME OF PERSON MAKING REQUEST AND THE SERVICE REQUESTED AND PERFORMED.

FOR OBSERVATION AND GUIDANCE, THE FOLLOWING CODES MAY APPEAR ON WORK ORDERS.

AI	- AGRI INDUSTRIES	
B1	- BAD ORDER	
BA	- BLASTING AGENT	-HAZARDOUS-
CA	- CARGILL	
CD	- CONDEMNED	
CB	- COMBUSTIBLE	-HAZARDOUS-
CL	- CHLORINE	-HAZARDOUS-
CM	- CORROSIVE	-HAZARDOUS-
DG	- DANGEROUS	-HAZARDOUS-
DH	- DO NOT HUMP	
DU	- DO NOT UNCOUPLE	
FH	- FLAMMABLE GAS	-HAZARDOUS-
FL	- FLAMMABLE	-HAZARDOUS-
FS	- FLAMMABLE SOLID	-HAZARDOUS-
FW	- FLAMMABLE SOLID W	
	- DANGEROUS WHEN WET	-HAZARDOUS-
HE	- HEAD END MOVEMENT	
HP	- HOUSTON PUBLIC ELEVATOR	
HV	- HIGH VALUE	
IP	- INTERCHANGE PROHIBITED	
IPSW	- INTRA-PLANT SWITCH	

MR - MECHANICAL REFRIGERATION
 MCNR - MECHANICAL CAR NOT RUNNING
 NG - NON-FLAMMABLE GAS -HAZARDOUS-
 NP - NO PLACARD REQUIRED
 OM - OXIDIZER -HAZARDOUS-
 OP - ORGANIC PEROXIDE -HAZARDOUS-
 OR - OTHER REG MATERIAL-HAZARDOUS-
 OX - OXYGEN -HAZARDOUS-
 PA - POISON GAS -HAZARDOUS-
 PB - POISON 'B' -HAZARDOUS-
 RE - REAR END ONLY
 RM - RADIOACTIVE MATERIAL
 REJT - CAR REJECTED BY SHIPPER
 RSPT - RESPOT DUE TO CARRIER'S ERROR
 TURN - TURN CAR & RESPOT
 UE - UNION EQUITY
 WH - WEIGH HEAVY
 WI - WAIVE INSPECTION-SET DIRECT
 WL - WEIGH LIGHT
 XA - EXPLOSIVES 'A' -HAZARDOUS-
 XB - EXPLOSIVES 'B' -HAZARDOUS-
 XX - DO NOT MOVE THIS CAR

GOOD COMMUNICATION AND COMPLIANCE WITH INSTRUCTIONS IS ESSENTIAL FOR A COMPLETE AND SUCCESSFUL CLIC OPERATIONS. YOUR COOPERATION IS SOLICITED AND APPRECIATED.

S T A T I O N I N D E X

STATION NAME	NUMBER	PAGE
BESSMAY	8770	2
BLEAKWOOD	9705	8
BOISE SOUTHERN	9732	16
BON WIER	9716	12
BUNA	8767	2
CALL	8779	4
CRAVEN	9757	30
DE RIDDER	9740	22
ELIZABETH	9772	34
FAWIL	9712	10
HITE	9737	20
IKES	9744	24
KIRBYVILLE	8784	6
LE VERTE	8775	4
MARKEE	9750	26
MERRYVILLE	9723	12
NEALE	9728	14
OAKDALE	9781	36
PITKIN	9762	32
QUINN	8761	2
SHEAR	9734	18
SUGRUE	9755	28

- E -

NAME

PAGE

I N D E X O F P A I R I N G S

INDEX OF PATRONS

NAME	PAGE
AMERICAN CYNAMID	16
BOISE SOUTHERN	16
CALCASIEU PAPER CO	34
CONNIE THOMAS SPUR	6
EAST TEX PULP	32
FUSSELL FEED CO	4
GOVERNMENT SPUR	12
HILLYER DEUTCH EDWARDS	36
INTERNATIONAL PAPER CO	22
KELLER WEBER CO	36
KIRBY LUMBER CORP	10
LA REFRIGERATION CORP	36
LOCKWOOD LUMBER CO	20
OAKDALE PLANING MILL	36
SOUTHLAND SPUR	6
SRN TRANSFER	2
STANLEY GATES	36
STIMITS FEED STORE	2
TEXACO	22

- F -

STATION NAME

NUMBER PAGE

STATION INDEX

ZONE 27 < QUINN 8761 > LONGVIEW DISTRICT

279800 LONGVIEW DISTRICT MAIN TRACK

ZONE 27 < BUNA 8767 > LONGVIEW DISTRICT

277000 BUNA SIDING

01	BUNA STIMITS FEED STORE (SACK FEED)	DOCK
02	BUNA STIMITS FEED STORE	PIT
03	BUNA STIMITS FEED STORE (SACK FERTZ)	DOCK
04	BUNA TEAM TRACK PATRONS	OPEN
05	BUNA TEAM TRACK PATRONS	OPEN

ZONE 27 < BESSMAY 8770 > LONGVIEW DISTRICT


278000 BESSMAY LONG SIDING

278100 BESSMAY SRN TRANSFER TRACK NO. 3


278200 BESSMAY SRN TRANSFER TRACK NO. 1

278300 BESSMAY SRN TRANSFER TRACK NO. 2

278500 BESSMAY TEAM TRACK



IDENTICAL POINTS



ZONE N^o. 27
SHEET 5 OF 5

PAGE 2
LONGVIEW DISTRICT

ZONE 28 < LE VERTE 8775 > LONGVIEW DISTRICT

289800 LONGVIEW DISTRICT MAIN TRACK
281000 LE VERTE SIDING

ZONE 28 < CALL 8779 > LONGVIEW DISTRICT

282000 CALL SIDING
01 CALL TEAM TRACK PATRONS
10 FUSSELL FEED WAREHOUSE

DOCK

LONGVIEW DISTRICT

LONGVIEW DISTRICT MAIN TRACK

KIRBYVILLE STATION NO. 1

KIRBYVILLE YARD TRACK NO. 2

KIRBYVILLE YARD TRACK NO. 3

KIRBYVILLE HOUSE TRACK

KIRBYVILLE HOUSE TRACK PATRONS DOCK

KIRBYVILLE OIL SPUR

KIRBYVILLE SOUTH AND SPUR

KIRBYVILLE C. W. THOMAS SPUR

LE VERTE

CALL

M
P
4
3

2810

2810

Dirt Road

2810

2898

2821

F.M. 1004

2898

2821

01

2821

Bridge

2820

2820

2898

2820

To Silsbee

To Longview

FUSSELL
FEED
WHSE.


LONGVIEW DIST.

ZONE 28


PAGE 4

ZONE 28 < KIRBYVILLE 8784 > LONGVIEW DISTRICT

289800 LONGVIEW DISTRICT MAIN TRACK
 283000 KIRBYVILLE SIDING NO. 1
 283100 KIRBYVILLE YARD TRACK NO. 2
 283200 KIRBYVILLE YARD TRACK NO. 3
 283300 KIRBYVILLE HOUSE TRACK
 01 KIRBYVILLE HOUSE TRACK PATRONS DOCK
 283400 KIRBYVILLE OIL SPUR
 283500 KIRBYVILLE SOUTHLAND SPUR
 283600 KIRBYVILLE CONNIE THOMAS SPUR
 409800 OAKDALE DISTRICT MAIN TRACK




KIRBYVILLE M.P. 524



ZONE 40 < BLEAKWOOD 9705 > OAKDALE DISTRICT

409800 OAKDALE DISTRICT MAIN TRACK
 400200 BLEAKWOOD TEAM TRACK
 01 BLEAKWOOD TEAM TRACK PATRONS

OPEN



BLEAKWOOD MP. 5.2

4002

MAIN LINE

U.S.

87

← To Kirbyville

To Oakdale →

OAKDALE DIST.

ZONE 40

SHEET 8

ZONE 40 < FAWIL 9712 > OAKDALE DISTRICT

409800 OAKDALE DISTRICT MAIN TRACK

400100 FAWIL KIRBY LUMBER CORP LEAD & TIE LOADING TRACK

01 FAWIL KIRBY LUMBER CORP

TIE LOADING

400500 FAWIL KIRBY LUMBER CORP PLYWOOD LOADING TRACK

01 FAWIL KIRBY LUMBER CORP

PLYWOOD LOADING

401000 FAWIL KIRBY LUMBER CORP CHIP LOADING TRACK


01 FAWIL KIRBY LUMBER CORP

O.H. SPOUT

402000 FAWIL SIDING

ZONE 40

PAGE 9



FAWIL
OAKDALE DISTRICT
ZONE NO. 40

ZONE 40 < BON WIER 9716 > OAKDALE DISTRICT

409800 OAKDALE DISTRICT MAIN TRACK
402100 BON WIER TEAM TRACK
01 BON WIER TEAM TRACK PATRONS
402200 BON WIER SIDING

OPEN

ZONE 40 < MERRYVILLE 9723 > OAKDALE DISTRICT


402300 MERRYVILLE SIDING NO. 1
402400 MERRYVILLE SIDING NO. 2
402500 MERRYVILLE GOVERNMENT SPUR
402600 MERRYVILLE OLD HOUSE TRACK
402700 MERRYVILLE HOUSE TRACK
01 MERRYVILLE HOUSE TRACK PATRONS

OPEN

ZONE 80 <NEALE 9728> OAKDALE DISTRICT

809900 NEALE MAIN TRACK

800100 NEALE PASSING TRACK (2610 FT)



27



8001

8099

8001 (2610')

8001

TO KIRBYVILLE


TO OAKDALE

NEALE
ZONE 80
PAGE 14

ZONE 80 <BOISE SOUTHERN 9732> OAKDALE DISTRICT

809900 BOISE SOUTHERN MAIN TRACK
800900 BOISE SOUTHERN RUN-A-ROUND TRACK
801000 BOISE SOUTHERN INDUSTRY LEAD
801100 BOISE SOUTHERN AMERICAN CYNAMID TRACK
 (BOISE SOUTHERN LEAD MP 5)
01 BOISE SOUTHERN AMERICAN CYNAMID CO.WHSE DOOR


NOTE: SANTA FE SETS OUT AND PICKS UP ON
BOISE SOUTHERN TRACK 7, 8, AND 9.



ZONE 81 <SHEAR 9734> OAKDALE DISTRICT

809900 SHEAR MAIN TRACK

802100 SHEAR PASSING TRACK (2130 FT)



ZONE 81 CHITE 9337 > OAKDALE DISTRICT

01 CHITE LOCKWOOD LBR CO
802500 CHITE LOCKWOOD LBR TRACT
802400 CHITE TEAM TRACT
802500 CHITE MAIN TRACT

OPEN

34

PVT XING

8099

8021 (2130')

8021

8021

TO KIRBYVILLE


TO OAKDALE

SHEAR
ZONE 80
PAGE 18

ZONE 81 <HITE 9737> OAKDALE DISTRICT

809900 HITE MAIN TRACK
802400 HITE TEAM TRACK
802500 HITE LOCKWOOD LBR TRACK
01 HITE LOCKWOOD LBR CO

OPEN



HITE
ZONE 80
PAGE 20

ZONE 81 <DE RIDDER 9740> OAKDALE DISTRICT

819900 DE RIDDER MAIN TRACK
811600 DE RIDDER TEAM TRACK
01 DE RIDDER TEAM TRACK PATRONS OPEN
811800 DE RIDDER KCS INTERCHANGE TRACK
812100 DE RIDDER STORAGE NO 1
812200 DE RIDDER STORAGE NO 2
812300 DE RIDDER RUN-A-ROUND NO 3
812500 DE RIDDER INT'L PAPER CO LEAD TRACK
812600 DE RIDDER WEST LEG OF WYE
812700 DE RIDDER INDUSTRY LEAD
01 DE RIDDER TEXACO WAREHOUSE DOOR
812800 DE RIDDER INDUSTRY TRACK

TO KIRBYVILLE

TEAM
01 8110

CROSBY RD.

DEPOT

KCS

INTERNATIONAL PAPER

TEXACO
01


39

TO OAKDALE

DE RIDDER
ZONE 81
PAGE 22

ZONE 81 <IKES 9744> OAKDALE DISTRICT

819900 IKES MAIN TRACK
813000 IKES HOUSE TRACK



IKES

ZONE 81

PAGE 24

ZONE 81 <MARKEE 9750> OAKDALE DISTRICT

819900 MARKEE MAIN TRACK

813200 MARKEE PASSING TRACK (2630 FT)



ZONE 81 OAKDALE DISTRICT

819900 SUGAR HAIN TRACK
813400 SUGAR STORAGE TRACK

50

8199
8132

8132

8132


TO KIRBYVILLE

TO OAKDALE

MARKEE
ZONE 81
PAGE 26

ZONE 81 <SUGRUE 9755> OAKDALE DISTRICT

819900 SUGRUE MAIN TRACK
813400 SUGRUE STORAGE TRACK



56

8134

8134

8199

8134

TO KIRBYVILLE

TO OAKDALE

SUGRUE
ZONE 81
PAGE 28

ZONE 81 < CRAVENS 9757 > OAKDALE DISTRICT


819900 CRAVENS MAIN TRACK
813600 CRAVENS HOUSE TRACK

TO OAKDALE

TO IDIRBYVILLE

819900 PITKIN MAIN TRACK
813800 PITKIN PASSING TRACK (2650 FT)
813900 PITKIN HOUSE TRACK
814000 PITKIN GOVERNMENT
814100 PITKIN EAST TEX PULP

OPEN



ZONE 81 <PITKIN 9762> OAKDALE DISTRICT

819900 PITKIN MAIN TRACK
813800 PITKIN PASSING TRACK (2650 FT)
813900 PITKIN HOUSE TRACK
814000 PITKIN GOVERNMENT SPUR
01 PITKIN EAST TEX PULP

OPEN


TO KIRBYVILLE

TO OAKDALE

EAST TEX PULP

PITKIN


ZONE 81
PAGE 32



ZONE 81 <ELIZABETH 9772> OAKDALE DISTRICT

819900	ELIZABETH MAIN TRACK	
815000	CALCASIEU MILL STORAGE TRACK	
815100	CALCASIEU PAPER MILL TRACK NO 1	
01	CALCASIEU PAPER CO	DOOR
815200	CALCASIEU PAPER MILL TRACK NO 2	
01	CALCASIEU PAPER CO	DOOR
815300	CALCASIEU BAG PLANT TRACK	
01	CALCASIEU BAG PLANT	DOOR
815400	CALCASIEU OUTSIDE BAG PLANT TRACK	
01	CALCASIEU BAG PLANT	DOOR
815500	CALCASIEU WOOD YARD MAIN	
815600	CALCASIEU LIME SPUR	
01	CALCASIEU LIME UNLOADING	DOOR
815700	CALCASIEU SALT CAKE SPUR	
01	CALCASIEU SALT CAKE UNLOADING	DOOR
815800	ELIZABETH PASSING TRACK (2140 FT)	
815900	ELIZABETH STORAGE TRACK	
816000	ELIZABETH HOUSE TRACK	
816100	ELIZABETH CALCASIEU PAPER PLANT LEAD	

ZONE 81 OAKDALE DISTRICT




ZONE 81 <OAKDALE 9781> OAKDALE DISTRICT

819900 OAKDALE MAIN TRACK
 01 OAKDALE LA REFRGS CORPN
 02 OAKDALE LA REFRGS CORPN
 816300 OAKDALE WEST LEG WYE & TAIL TRACK
 816400 OAKDALE EAST LEG WYE
 816600 OAKDALE INDUSTRY TRACK
 01 OAKDALE PLANING MILL
 816700 OAKDALE HED WEST LEAD
 816800 OAKDALE HED INDUSTRY LEAD
 816900 OAKDALE MP INTERCHANGE TRACK
 817000 OAKDALE HOUSE TRACK
 01 OAKDALE KELLER-WEBER CO
 02 OAKDALE KELLER-WEBER CO
 817100 OAKDALE SIDING NO. 1 (2139 FT)
 817200 OAKDALE STORAGE NO 2.
 817300 OAKDALE STORAGE NO 3.
 817400 OAKDALE ENGINE TRACK

DOOR
DOOR

DOOR

DOOR
DOOR



OAKDALE
ZONE 81
PAGE 36