

✓ 205 = 6 R8 nos

✓ 17 = 4 Black B-367 nos

24 = 5 WO expres

No 376 = 30 Pn Exp late
2500 water
45 Parker off for box
20 H₂O water

Kn-1 = 30 w wave

No 324 = 18 ma work
12 wa "
10 Allen's left
10 " no 52
26 Am no 55
20 W8 Ek 524 last
30 Buck for wave
35 W8 no 57
25 Sw light
20 W Signals

RZ-1 = 15 D work
105 Do " #7, #214
20 BS "
40 DE "
25 Luffo Pit work
15 N "
20 CD "
20 NX "
65 WO "
10 MS "

RZ-2 = 15 Ba swg

Ra-1 = 10 Pn train
at-2 = 15 on set off + pit
23 JR pit + pick up
30 Hi #52 #10 #14
30 U coal + water
40 KN set off, pit + swg
40 Fa coal shouldered, water + brake test
35 DB pit, pick up + swg

377x = 160 SW work